


Control Center Series 30 User Manual

For CCS30 Version 1.1






Index

1 Installation	4
1.1 Microsoft .Net 2.0.....	4
2 General Functions	5
2.1 Search for Devices.....	5
2.1.1 Default Search	5
2.1.2 Advanced Search.....	6
2.2 Remove Device	6
3 Measuring	7
3.1 Current Measurement Values.....	8
3.1.1 Box View	8
3.1.2 Tabular View.....	9
3.2 Performing a "New Measurement"	10
3.2.1 Configuring a Measurement.....	11
3.2.2 Measuring.....	12
3.2.3 Saving / Loading / Adding measurements.....	15
3.2.4 Exporting Measurements.....	15
4 Configuring Devices	16
4.1 Configuring Individual Devices.....	17
4.2 Configuring Devices using General Bus Address 250	18
4.3 Configuring Multiple Devices Simultaneously	19
5 Program Settings	20
5.1 General	20
5.2 Pressure Unit	21
5.3 Communication Port (Comport) Overview	22
5.4 Parameters at Program Start	22
5.5 Login.....	22



Quick Search




No.	Function	Page
1	Search for device	5
2	Remove device	6
3	Configure device	15
4	Start new measurement	7
5	Display current measurements	8
6	Existing devices	-




1 Installation

Download the software using the Keller installer. The setup program now starts automatically. Follow the setup instructions.



1.1 Microsoft .Net 2.0

At the start of installation you are asked to install the required Microsoft .NET 2.0 software, if it is not already present. The files that are needed are downloaded directly from Microsoft.





2 General Functions

2.1 Search for Devices

The device address and other search parameters can be defined when searching for devices, whereby the default search setting (Auto) is usually sufficient. The advanced search allows additional settings to be made for the serial interface.

The device list is regenerated during the default search.

2.1.1 Default Search

The interface (Comport), baud rate and an address range can be specified for the default search.


Interface: auto Baud Rate: auto Address: (e.g.: 30-35 88) 9-11 Devices... Search

If a value has been set to "auto", the search is carried out using all possible variants. If several Comports are available, they are searched through simultaneously.

The following settings can be made for the "Address" field:

Entry	Meaning
auto	The search is carried out using bus address 250. All devices that are connected to the bus reply when this address is used. If communication takes place using the "auto" setting (address 250), only one device may be connected to the bus.
1	Devices are searched for with an address of 1.
1-30	Devices are searched for with addresses of 1, 2, 3,... 29, 30
1, 5	Devices are searched for with addresses of 1 and 5.
1, 7-18, 241	Devices are searched for with addresses of 1, 7-18 and 241.

The progress for each Comport is shown in the status line during a search:





2.1.2 Advanced Search

An advanced search can be carried out with modified Comport settings (parity bit/stop bit).

The advanced search is activated using "View" → "Advanced":

The screenshot shows a configuration dialog box with the following fields and controls:

- Interface: auto (dropdown)
- Baud Rate: auto (dropdown)
- Parity-Bit: None (dropdown)
- Stop-Bit: One (dropdown)
- Address: (e.g.: 30-35 88) 9-11 (text input)
- Devices... (button)
- Search (button)

The default settings are: No parity bit (none) and 1 stop bit.

2.2 Remove Device

All selected devices are removed from the device list using the "Remove" button.

The screenshot shows a table of devices with the following columns: SN, Range, Device-Type, and Address. The table contains three rows of data. The second and third rows are selected. To the right of the table are buttons for Search, Remove, and Configure. A red arrow points to the Remove button.

SN	Range	Device-Type	Address
189	0.10 - 21.00 bar	Lex 1	COM8: 10
63782	0.000 - 10.000 bar	S30X	COM1: 9
119630	0.000 - 10.000 bar	S30X	COM1: 11




3 Measuring

Two different measuring types are available.

“New Measurement” [1]: Measurements can be carried out with advanced measuring parameters (interval, data storage, etc.) using this option.

“Current Meas. Values” [2]: The current measurements for all connected devices are displayed.





3.1 Current Measurement Values


This window provides a rapid overview of all connected devices and their measurement values. Two different views are available:

3.1.1 Box View

The box view is used for device monitoring. The individual boxes (devices) can be moved by dragging them and grouping/arranging them as required.


Minimum and maximum limits can be set. As soon as these values are undershot or exceeded, the relevant channel is highlighted in a particular color. The min./max. values and the colors can be modified by right-clicking on the channel ("Edit Colors").

Individual channels can also be hidden using this menu.




Note:

If a device is no longer visible on the user interface (e.g. it has been pushed out of the display area), the device can be deactivated and activated again by right-clicking on the background. This puts the device back into the visible area.



3.1.2 Tabular View

This is where the current measurements (channels) are displayed and can be conveniently checked and compared.






3.2 Performing a "New Measurement"

The measurement display is divided into two different areas. On the left there is the control area for starting, stopping and configuring the measurement, and on the right there is the data area for displaying the measurement data. Clicking on "Start" causes a new measurement to be performed with all available channels of the selected devices.

The control area on the left contains the name of the measurement, the current measurement values for the individual channels, the measuring interval and the file in which the measurement data is stored. The measured channels can be stored in the form of a graph or a table.



The measurement settings can be modified using the "Config. Measurement" button. The settings can only be changed if measuring has been stopped beforehand.



3.2.1 Configuring a Measurement

If you click on "Config. Measurement" the configuration screen is displayed:

The screenshot shows the 'Measurement' configuration window. The 'Measurement' dropdown is set to 'bar'. The 'General' section has 'Measuring Interval' set to 2 ms, 'Save Data' unchecked, 'Savepath' set to 'C:\Dokumente und Einstellungen\KoelbenerD\Eigene Dateien\New Measure 18', and 'Save Interval' set to 5 s. The 'Info' section has 'Name' set to 'New Measure 18.01.10'. The 'Measuring Channels' section shows two channels: '10 : 26999 (S30X)' and '11 : 119630 (S30X)' on the left, and '9 : 63782 (S30X)' on the right. There are navigation buttons (>>, <<), an 'All' checkbox, a 'P1' field, and a 'Channel Visualisation' section with 'Color' and 'Symbol' options. Red callout boxes with numbers 1, 2, and 3 point to the 'Measuring Interval', 'Name' field, and 'Channel Visualisation' section respectively.

General [1]

The measuring interval can be specified in milliseconds, seconds, minutes or hours.

The smallest read-out interval is device-dependent. With devices with a baud rate of 115,200 baud the fastest readout speed is 3 ms/channel. If the interval is smaller than the read-out speed specified by the device, the device is read out using the fastest possible speed.

Activating "Save Data" causes the measurement data to be saved continuously.

Attention: Many measurement values and large files

The CCS30 is extremely powerful, and it is easy to collect large quantities of data that are subsequently difficult to process. Excel cannot handle more than 65000 measurements per channel. At a measuring speed of 3ms with one channel, this quantity is reached in just 3 minutes and 15 seconds.



Approximately 70kb of metadata is generated for each connected device. Each measurement requires 20 bytes of storage space. The file for the measurement with one transmitter with 65000 measurements is 1.37 MB in size.

Info [2]

The name of the measurement and the description can be entered as required.

Measuring channels [3]

All existing devices/channels that are not yet involved in measuring can be seen on the left-hand side. The list on the right shows devices/channels that have been selected for the measurement. The devices/channels can be moved to the relevant side by dragging, double clicking or single clicking (followed by ">>" or "<<").

Measuring

Clicking on "<<Measure" takes you back to the original view.

3.2.2 Measuring

The screenshot shows the 'Measurement' software interface. The main window displays a graph titled 'New Measure 15.01.10' with two y-axes: Pressure (bar) on the left and Temperature (°C) on the right, and Time on the x-axis. The graph shows a blue curve for pressure and a green curve for temperature. A context menu is open over the graph, listing options: 'copy to clipboard', 'Save as', 'zoom back', 'set zoom to default', 'Set scaling to default', and 'Properties'. The interface includes a left-hand panel for channel selection and a right-hand panel for graph controls. Red arrows and numbers 1-6 highlight specific features: 1 points to the channel list, 2 points to the graph, 3 points to the Properties button, 4 points to the context menu, 5 points to the Table button, and 6 points to the Update Values button.


Channel	Value
11:119630 (S30X)	
<input checked="" type="checkbox"/> P1	0.9643
<input checked="" type="checkbox"/> TOB1	24.69
<input checked="" type="checkbox"/> CH0	0.9800



The current measurements are displayed on the left during the measurement [1]. The relevant channels are revealed or hidden in the graph by activating or deactivating the check boxes. The graphical display [2] shows the channels as per the configuration. The channels can be individually scaled by clicking on "Properties" [3]. Right-clicking on the graphs opens a pop-up menu [4] containing different options for viewing/saving the graphs. The tabular view can be called up using the "Table" tab [5].

It can take a considerable time to update the graph if large quantities of data are involved. In this case a message is displayed saying that the graph is no longer being automatically updated. Updating now takes place using the "Update Values" button [6]. This function prevents re-drawing of the graph (which may be time-intensive) from affecting the measuring interval.

In order to make it possible to compare channels to each other, the individual channels can be scaled manually. These settings can also be changed during an active measurement.



Scale channels [1]

The gain and the offset can be modified for each channel.



Scale graph [2]

- A minimum and a maximum can be specified for the Y-axes.
- The window width can be defined.
- The legend can be displayed.
- The description of the measurement can be displayed (this is useful if the graph is being stored as a "Print Screen" image)

Tabular view of measurement data:

Measurement bar

Measurement Name: New Measure 15.01.10

Channels: 11:119630 (S30X)

- P1
- TOB1
- CHO

Intervall: 00:00:00.0020000

Save to File:

Stop Start

Delete Measurement

Config. Measurement >>

Zeit (119630:CHO)	119630:CHO	Zeit (119630:P1)	119630:P1
15.01.2010 09:59:19.736	0.9820	15.01.2010 09:59:19.647	0.9643
15.01.2010 09:59:19.867	0.9820	15.01.2010 09:59:19.780	0.9643
15.01.2010 09:59:19.999	0.9820	15.01.2010 09:59:19.911	0.9643
15.01.2010 09:59:20.131	0.9820	15.01.2010 09:59:20.043	0.9643
15.01.2010 09:59:20.265	0.9820	15.01.2010 09:59:20.177	0.9643
15.01.2010 09:59:20.396	0.9820	15.01.2010 09:59:20.308	0.9643
15.01.2010 09:59:20.528	0.9820	15.01.2010 09:59:20.440	0.9643
15.01.2010 09:59:20.660	0.9820	15.01.2010 09:59:20.572	0.9643
15.01.2010 09:59:20.791	0.9820	15.01.2010 09:59:20.703	0.9643
15.01.2010 09:59:20.923	0.9820	15.01.2010 09:59:20.835	0.9643
15.01.2010 09:59:21.055	0.9820	15.01.2010 09:59:20.967	0.9643
15.01.2010 09:59:21.189	0.9820	15.01.2010 09:59:21.101	0.9643
15.01.2010 09:59:21.320	0.9820	15.01.2010 09:59:21.233	0.9643
15.01.2010 09:59:21.452	0.9820	15.01.2010 09:59:21.364	0.9643
15.01.2010 09:59:21.584	0.9820	15.01.2010 09:59:21.496	0.9643
15.01.2010 09:59:21.715	0.9820	15.01.2010 09:59:21.628	0.9643
15.01.2010 09:59:21.846	0.9820	15.01.2010 09:59:21.758	0.9643

Show all Time Scales

Refresh << < 1 > >>

Graph Table

Since the measurements are not all made at exactly the same time, a time is also allocated for each measurement. All time axes apart from one can be hidden in order to provide an organized display [1]. The table can be updated by clicking on "Update" or automatically when a new page is selected [2]. The pages can be called up by directly entering the page number or using the "<< < > >>" buttons. Approximately 15,000 measurement values can be displayed per page of the table.

Note:

The graph can display a maximum of 5,000,000 measurements, after which it is deactivated and the measurement values are only shown in a table.



3.2.3 Saving / Loading / Adding measurements

The measurement values can be saved continuously during the measurement (→ 3.2.1 Configuring a Measurement) or at the end of the measurement using the "Measurement" → "Save" menu. An old measurement is also loaded using the "Measurement" → "Load" menu.

Old measuring data can be added to the current measurement. This allows an old measurement to be continued ("Measurement" → "Add").

3.2.4 Exporting Measurements


Measurements can be exported as CSV and subjected to further processing with Excel or a similar program. The export is carried out using the "Measurement" → "csv-Export" menu.



4 Configuring Devices


In order to configure a device, it is selected and the individual parameters are modified. Several devices can also be configured simultaneously.

Select the required device(s) and then click on "Configure":



(Double clicking on the relevant device with the mouse also takes you to the configuration facility).

The configuration screen is divided into three areas:



1. Device and unit selection
2. Information about the selected device
3. Configuration area



4.1 Configuring Individual Devices

If an individual device is selected in the main window, it is automatically selected in the configuration window (see figure above).

Modifying the parameters:

Tab	Parameter
Zeroing / current values	The available measuring channels for the devices are listed and the current measurement is displayed. Channels can be zeroed here.
Communication	Bus address
Advanced	Different parameters are listed depending on the device. If no parameters are available, this Tab is hidden. Possible parameters: <ul style="list-style-type: none">- Temperature compensation- User units- Block/release pressure units- Starting pressure unit of device- Display resolution
CH0	Channel 0 configuration (with which calculation is possible)
Analogue output	Scaling of analogue output
Switch output	Configuration of switch output



4.2 Configuring Devices using General Bus Address 250

If "Address 250" is selected under "Configuration" (instead of the serial number), the same configuration can be written to several devices in sequence. Only one individual device may be connected to the bus (to the interface) if this configuration type is used.

Procedure: First connect a master device and click on "Read out Master". This specifies the available configuration parameters to the program.

Now modify parameters if necessary and click on "Write". Remove configured device from the interface. Then connect and describe the devices to be configured one after the other.

1. Select "Address 250"

2. Select Comport

3. Select baud rate

4. Read out master


1. Select "Address 250"
2. Select Comport
3. Select baud rate
4. Read out master



4.3 Configuring Multiple Devices Simultaneously

If multiple devices are being configured simultaneously, the devices that are connected to the same Comport must have different addresses and the same baud rate.

This function makes it possible to perform simultaneous zeroing of multiple devices (within a few milliseconds), for example.



1. Select "Multiple devices"
2. Select required devices
3. "Run" the configuration

If a configuration setting can only be made for one device (e.g. zeroing P2) it is only carried out for this device. The remaining devices are unaffected.




5 Program Settings

This is where general program settings are made that do not have a direct influence on the measuring data or the device configurations.

5.1 General

Selecting the "Tools" → "Settings" menu item takes you to the general program settings:



Load old Devices at Program Start:

The list of devices is empty when the program starts. If the devices that were being used when the program was last exited are to be displayed, activate "Load old Devices at Program Start".

"Delete old Devices at Search"

During a search for new devices the device list is cleared if "Delete old Devices at Search" is activated.

Scaling Steps:

The scaling steps define the resolution with which the measuring data is to be displayed.

Resolution = (PMax–PMin)/scaling steps

Language:

This is where the language is selected.

Log Level:

Important messages are stored in a log file. The number of entries is selected by adjusting the log level.


Comport-Timeout / TCP/IP-Timeout:

Specifies how long the CCS30 program waits for a reply from the device. Too small a value can lead to missing measurements. We recommend the value shown above.




5.2 Pressure Unit

The displayed pressure unit can be modified in different locations in the program. The measuring data is always measured and saved in bar, but it is possible to change the display to a different unit.



The conversion factors and an offset can be set for a unit using the "Tools" → "Units" menu option. The unit can also be deactivated and therefore no longer appears for selection in the program. [1]

It is possible to add your own units [2].





5.3 Communication Port (Comport) Overview

The Comport settings can be displayed via "Tools" → "Comport overview":

Comport	Baud Rate	Echo	Parity	Stop-Bit	Open	Save-Mode
COM1	9600	False	None	One	False	
COM4	9600	True	None	One	False	
COM8	9600	True	None	One	False	

Close

5.4 Parameters at Program Start

The Control Center can be started with parameters. The following parameters are possible:

Parameter	Meaning
[Measurement file name]	Automatically opens the specified file.
-run=[Measurement file name]	Automatically opens the specified file and continues the measurement.

5.5 Login

The CCS30 program has other configuration options. This extension is enabled using "Tools" → "Login" followed by a password entry.

The password is: "prof"