The "KOLIBRI Desktop" software is part of the modern KOLIBRI product line which embeds the newest technologies and strives for intuitive design. This software runs on Windows and lets users read out and configure KELLER data loggers. With 'live data', a connected device can record directly to the PC. Selected measurement data can be graphically displayed and exported to various formats.

During the installation process please install the "FTDI Chip CDM Drivers" when using the KOLIBRI Desktop together with Dataloggers.
Only install "Manometer driver (LEO 5 USB) when using the KOLIBRI Desktop together with the "LEO 5" Manometer.

KELLER




A KELLER device should be recognized automatically. Otherwise please 'restart the search for devices'.




All records of datalogger devices can be read out and are stored on the PC as "Data record".




Use 'Live data' to make a new set of measurement with a connected device. This new data record is also stored.




Various device configurations can be made in 'DEVICE CONFIG'. Use the button to write configurations down to the device.




Select from all the stored data records one or multiple to visualize or export. Search, filter and arrange for properties.




Visualize the chosen data record/s and enhance the chart with various possibilities.




Export the chart to various export formats including Excel and Word-report. The used Date-Time depends on the set timezone.




Use the SETTINGS to customize the SW to your use case and application's need.